State of Wisconsin Department of Natural Resources PO Box 7291, Madison WI 53707-7291 dnr.wi.gov

Wadeable Macroinvertebrate Field Data Report Form 3200-081 (R 8/14)

Page 1 of 2

Instructions: Bold fields must be completed.

Station Summary							
Waterbody Name			Waterbody ID Code		Sample ID (YYYYMMDD-CY-FD)		
PIONEER VALLEY CREEK			883100		20171004-23-01		
Sampling Location					Database Key		
100 m upstream of CTHO					150693523		
SWIMS Station ID SWIMS Station Name							
10037209 PIONEER VALLEY CREEK AT CTH O							
Latitude Longitude Lat/Long Determination Method (circle)						Datum Used if using GPS	
42.83814 89.65573			SWIMS SWDV GFS			WGS84 or NAD83	
			shed Name			County	
I			SUGAR RIVER			GREEN	
Sample and Site Descriptors							
Sample Collector (Last Name, First)				Project Name			
AMRHEIN, JAMES LEGLER SCHOOL AND PIONEE						ER VALLEY TWA 2017	
Sampling Device							
X D-Frame Kick Net Surber Sampler Eckman							
Ponar Artificial Substrate He				Hess Sampler	Other:		
Habitat Sampled			_				
Riffle Run Pool							
Other Shoreline Composite Proportionally-Sampled Habita					tat		
Littoral Zone Profundal Zone Wetland							
Total Sampling Time (min) Estimated Area Sampled (m²) Number of Samples in Composite							
2	2			1	١,	Replicate No of	
Reason For Sampling							
Least Impacted Reference X Baseline Impact / Treatment Site							
Control Site Other:							
Water Temp. (C) D.O. (mg/l) D.O	. (% sat.) pH	(su)	Conduc	ctivity (umhos/cm)		Transparency (cm)	
13.5 9.20	88.2 -	7.96		595		. 1	
Water Color Estimated Stream Velocity (m/s)						15-	
Clear Turbid Stained				Slow	Fast		
THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	old Stain	ea		(< 0.15 m/s)	(0.15 m/s	s - 0.5 m/s) (> 0.5 m/s)	
		verage St	tream De	epth of reach (m)	Average	Stream Width of reach (m)	
m/s or f/s							
Composition of Substrate Sampled (Percent):							
			Rubble			Gravel	
Bedrock:(basketball or larger):			(tennisball to basketball):((ladybug to tennisball):		
Sand: Clay:				Silt/Muck: Overh		hanging Vegetation:	
Aquatic Macrophytes: Leaf Snags: C				Woody Debris:		Other ():	
						/-	
Embeddedness of Substrate at Sample Site (%) Canopy Cover at Sample Site (%)							